










P/E TAMAN IMPIANA 1



- Petunjuk: (Sedia ada)
-  Sesalur Atas VR ABC 3x185+120+16mmp
 -  Tiang konkrit 9.0m
 -  Peti Pembekal 1600A (TX1)

- Petunjuk: (Cadangan)
-  Sesalur Atas VR ABC 3x185+120+16mmp
 -  Sesalur KakiLima PVC 19/064 (35mmp)
 -  Tiang konkrit 9.0m
 -  Black Box 160A
 -  Corrugated 100mmp Open Cut Tar (180m)
 -  Stay

P/E TAMAN IMPIANA 2



Kawasan: BIDOR Daerah:
No. Fail : 110000891038

FARLIM GROUP FASA 2B

ALL RIGHTS RESERVED
LUKSIAN IM TAMAN BOLEH DIBANGUN
TANPA PERSEKUTUAN DARI SUKUTERA
TENAGA NASIONAL BERHAD

Pindaan	Dilukis : SHAHR	Diluluskan : EN INRAM
	Disemak : EN ZADNI	Tarikh : 06/3/23
	No. Lukisan :	