


**KORIDOR  
UTILITI**  
DARUL RIDZUAN




**TENAGA  
NASIONAL  
BERHAD**

**PERMOHONAN BAGI MENDAPATKAN KEBENARAN  
MENJALANKAN KERJA MSVT - PENUKARAN ALAT  
SUIS TIADA GAS KEPADA RMU BARU DAN  
REKONFIGURE VOLTAN RENDAH DI PE BT 10 LEKIR**

**LOKASI:  
JALAN BT 10 LEKIR**

**NO. RUJUKAN TNB:  
D-SIT-S24-4876**

**APRIL 2025**



PATOD BT10 LEKIR  
4.127763, 100.757997



HDD 2 PAIP 30M X 1.2 = 36M

NO TIANG  
PPU 12

NO TIANG  
PPU 13

Google Earth

Image © 2024 Airbus

**KETERANGAN**

- CAD. BARU UG CABLE, 1KV, 4C 185MMP XLPE
- TIANG SPUN SEDIADA 9M



NEGERI : PERAK      SUBZONE : SERI MANJUNG  
No FAIL : D-SIT-S24-4876

KELUARAN PERTAMA  
Dilukis oleh: ABD RAZIF  
Disemak oleh: AFSANI  
Diluluskan oleh: FIRDAUS  
Tarikh: 4/3/2024

MSVT PENUKARAN ALATSUIS TIADA GAS KEPADA RMU BARU DI PATOD BT10 LEKIR

NO. FAIL ; PELAN 2